Using 3D Printed Parts! WARNING!
Resin is MORE BRITTLE than plastic!
Take GREAT CARE cutting supports!
Use SHARP cutters, squeeze GENTLY!
Clean up contact points with a fine file.
Glue with cyano or epoxy.
Prime and paint with normal paints.

www.flyingstartmodels.com