





**Includes Extensive Photos of Clipped-wing Corsair I!** 

# EC#152

# F4U-1 BIRDCAGE CORSAIRS

Nearly 2000 F4U Corsairs were pressed into service with the Fleet Air Arm (FAA) under a Lend-Lease agreement. Of these, 95 were birdcage variants that were designated Corsair 1s. Training was conducted in the U.S. at Quonset Point or Brunswick before the aircraft shipped to the UK.

These aircraft were painted in FAA equivalent colors using U.S. stocks with Vought using Dupont paints. While ANA colors were specified, in some cases there is not an identical match to similar more common FS colors used today. Like German WW2 aircraft, color interpretations of these Corsair 1s are controversial. Modelers should study available references so as to make there own educated assumptions.

#### Gus's Gopher

### BuNo 02324

White 10

VMF-213

July 1943

Pilot: 1st Lt Wilbur "Gus" Thomas. The unit's most successful ace, Thomas is credited with 18.5 victories, 3.33 probables and 3 damaged. This Marine Corsair not fitted with tail arresting gear.

Colors: Uppersurfaces: Blue Gray FS35189 Lowersurfaces: Light Gray FS36440 Prop Hub: Natural Metal


References: Corsair Aces of World War 2

Photos and flight log from private
collection published herein.

	Quel 1945.							
W610 B	Sain	I	1	7	芝	Past 1	PARROTTERS	******
	15	FALL	02513	20	J	Thomas	_	Broken Blod shillandown
	1.17		04.524	13	7		min.	Corott Boules - Wilde
	10	-		37	7		-	6
	18		02.492	7	R		_	test
	121		22.527	28	K		-	Strofting - Bairsto
	22	-		37	$\tau$		-	Bombes Geort - Xihiti
11	23			35	J		-	Burger Frederick - Rendora
翻り	41		-	20	d		-	
	44		-	10	J		-	
581	25			35	J		_	
	43	-	0218	2.1	7			Bomber Great - murkey
	666		325M	15	U	+	-	Same Polant - Bendara

Above: Pilot Thomas' Flight Log indicating BuNo 02324 as White 10.

Pilot "Gus" Thomas posing with White 10 in Summer 1943, starboard view.





JT 152

3BH

738 Sqn

1943

Colors: Uppersurface camouflage: ANA 613 Olive Drab similar to FS34130 ANA 603 Sea Gray similar to FS36173

Lowersurfaces: ANA 602 Sky Type S Gray similar to FS36440 Prop Hub: Unknown

References: Private photo published below.



3BH JT 152 in a photograph dated 15 April 1944 and taken at Lewiston, Maine. The specific history of this aircraft has proven difficult to discern from aircraft records as it appears to be confused with other aircraft near the same serial number.

JT 150

1943.

5 F

1835 Sqn

1943

172 collided after a brake failure while taxiing. Repaired, it went on to have a Cat "Z" take-off collision with JT 170 on 11 Oct

Colors: Uppersurface camouflage: ANA 613 Olive Drab similar to FS34130 ANA 603 Sea Gray similar to FS36173 Lowersurfaces: ANA 602 Sky Type S Gray similar to FS36440

Prop Hub: Natural Metal References: Private photos published on insert enclosed

Research provided by Mark Proulx

© 2013 Eagle Editions Ltd. All images/photos copyrighted by Eagle Editions Ltd. LLC

Assigned to 1835 Sqn at Quonset Point during August, 1943. It was involved in Cat "X" accident on August 25th when 5 P, JT

#### P.O. Box 580 Hamilton MT 59840 www.eagle-editions.com

No copies may be reproduced without written consent from publisher Eagle Editions Ltd. LLC The color schemes depicted are the artist's interpretations of the available photographic references only. The final decision resides with the modeler.

## EagleCals #152, photo insert for JT 150, 5 F - 1835 Sqn. Private collection

View of Corsair I, 5 F, JT150 of 1835 Sqn. clearly showing clipped wing feature of the aircraft and its unusual camouflage pattern. The aircraft arresting gear is visible.

MARK PROUEX PHOTO



Despite the obvious flaw on the original photo, the non-standard camouflage pattern with scalloped edges applied to this aircraft is still visible. Notice the white taping and clear framing at the aft end of the sliding canopy.

This unusual rear view reveals the scalloped edges of the camouflage pattern carried forward onto the upper surfaces of the wings. Just visible are black wing walks on the uppersurfaces of both wings.



In a rare starboard view, it can be seen that the paint scruffing at the wingroot and boarding step are indicative that the aircraft is not freshly painted.

MARK PROULX PHOTO