

EAGLE STRIKE


48236



VOODOO

Flight

bt
VOODOO
VOODOO
VOODOO
VOODOO
VOODOO



Suggested Kit: Monogram - 1:48 F-101 Voodoo.


VOODOO

Flight

Part 2


F-101B - 91 - MC Voodoo 57-0322 444th. Fighter Interceptor Squadron.

Kit Modifications: **Remove** all formation tape light strips Antenna, Beacons aft of the canopy and on forward fuselage. Also, belly Beacon. Green main landing gear doors.



F-101B - 115 - MC 59-0424 'I love NY' 136th. Fighter Interceptor Squadron, 107th. Fighter Interceptor Group.

New York ANG, New York State. This A/C had formation light strips but no turbine warning Red band.



References:

1. Voodoo. Modern Military Aircraft, Lou Drendel & Paul Stevens, Squadron/Signal Publications
2. McDonnell Douglas F-101 Voodoo, Famous Airplanes of the World No. 59, Bunnin-Do
3. F-101 Voodoo Variants, Robert F Dorr, Wings of Fame No 1, Aerospace Publishing.
4. Replica in Scale Vol.2 No.1, Fall, 1973, Stevens, Friddell, Wogstad.
5. Research by Norris Graser.

Recommended Kit:

1. Monogram - 1:48 F-101 Voodoo

Decaling: Apply decals only to a glossy surface.

1. With a sharp scissors or knife, carefully cut item to be used, being careful of not cutting off the clear film around it or that belonging to an adjacent item.
2. Submerge in clean tap water for over 10 seconds and lay over an absorbent paper towel. Decal will slide freely in about 20 seconds. Do not leave decal on water bowl over ten seconds, or adhesive quality will suffer.
3. With a clean brush, apply a setting solution to the area where the decal will finally lay. (Micro, Super or Aero Set will do). With a clean pointed brush slide the decal on to the final area. Allow the setting solution to dry for about 3-5 minutes.
4. With another clean brush, apply a solvent solution over the decal (Micro, Super or Aero Sol will do). Do this if possible in one stroke since your decal will soften up and wrinkle immediately. This is an important step in the process, whatever you do **DO NOT TOUCH THE DECAL**, after this process until it is totally dry, preferably overnight.
5. When thoroughly dry, rinse your model with tap water and mild soap to wash of excess glue.
6. Finish your model with the desired final coat (gloss, flat, or semi-gloss).

Aires offers super-detailing accessories for this and many other subjects in their range. Check our website at www.AeroMaster.com for this and many other wonderful products! Available To You Now!

