












AV-8B
Harrier II



Panel marking placement



Dotted panel is located on the aft section of the fuselage not the vertical stabilizer



AV-8B Technical assistance courtesy of Bruce Marschall MCDONNELL DOUGLAS Saint Louis, MO.