

EAGLE STRIKE



48149


# Last Wild Weasel Phantoms



Suggested Kit: Hasegawa/ESCI F4G Wild Weasel Phantom




# Last Wild Weasel Phantoms



COUPON  
AeroMaster  
(see website for details)



F-4G of the 190 FS/124 FW.  
Adorned with a colorful sharkmouth design, this F-4G "Wild Weasel" Phantom (69-7557) (above & left) of the 190FS/124FW wears Dark ("Gunship") Gray FS36118 over Medium ("Neutral") Gray FS36270.



F-4G of the 561 FS/57 W.  
Wearing a large cartoon "Wild Weasel" on its port intake, F-4G Phantom (69-7232) (below & left) of the 561FS/57FW again wears the standard USAF Dark Gray FS36118 over Medium Gray FS36270.




F-4G of the 561 FS/57 FW.  
Sharkmouthed F-4G Phantom (69-7295) (below & left), also of the 561FS/57FW, again Dark Gray FS36118 over Medium Gray FS36270. This machine was painted to commemorate the F-4 family's 33-year USAF service. Paint the forward nose pod Gloss Black before applying decals 32 and 33.

## COLOR SCHEMES



12902 SW 132nd Ct. Miami, FL. 33186 U.S.A  
Ph: (786) 293-0411, Fax: (786) 293-5822.

G (A/C 1)  
H (A/C 2 & 3)



Gear Door Numbers  
(see side views)

Burnt  
Metal

G (A/C 1)  
H (A/C 2 & 3)

### References:

- Research and photos from Mr. Norris Graser.

### Recommended Kits:

- Hasegawa/ESCI F4G Wild Weasel Phantom.

**Decaling:** Apply decals only to a glossy surface.

1. With a sharp scissors or knife, carefully cut item to be used, being careful of not cutting off the clear film around it or that belonging to an adjacent item.
2. Submerge in clean tap water for over 10 seconds and lay over an absorbent paper towel. Decal will slide freely in about 20 seconds. Do not leave decal on water bowl over ten seconds, or adhesive quality will suffer.
3. With a clean brush, apply a setting solution to the area where the decal will finally lay. (Micro, Super or Aero Set will do). With a clean pointed brush slide the decal on

to the final area. Allow the setting solution to dry for about 3-5 minutes.

4. With another clean brush, apply a solvent solution over the decal (Micro, Super or Aero Sol will do). Do this if possible in one stroke since your decal will soften up and wrinkle immediately. This is an important step in the process, whatever you do **DO NOT TOUCH THE DECAL**, after this process until it is totally dry, preferably overnight.

5. When thoroughly dry, rinse your model with tap water and mild soap to wash of excess glue.

6. Finish your model with the desired final coat (gloss, flat, or semi-gloss).

**48149**

Catch us on the net!



www.EagleStrikeProductions.com

COUPON  
EAGLE STRIKE

